

# Typical Failure on Metal Roofs

---

Photo Record



## Steel Roof

---

- Rust
- Vertical Cracks
- Blistering
- Roof Bolts





# Steel Roofs

---

- Rust on Ridge Cap
- Blistering
- Unkeyed Brush marks





## Steel Roofs

---

- A Typical Roof is Painted With Three Coats of Roof Paint
- An Eco Rubber Roof is applied at 1mm thick continuously pumped at extremely high pressure, the equivalent of nine standard layers. It sticks, is elastic and is UV resistant! Available in various colours

