



# GENERAL ECO RUBBER PRESENTATION

**SMALL ROOFS**

# LEAKY ROOF ON INSPECTION



GARAGE AREA = 61



TOTAL ROOF AREA = 177




DWELLING ROOF = 116

PARAPETS = 15, MEMBRANE = 192, KILOGRAMS REQUIRED = 230, INCLUDING CHIMNEY AND PREPARATION MATERIAL

## SOME DETAILS



MISALIGNED ROOF SHEETS – BIG GAPS  
CRACKED AND LOOSE 'LAP EN PAP'  
LENGTH CRACKS IN VARIOUS PLACES



PONDING AT CHIMNEY ROOF SEALING  
WITH DAMP LOOSE PAINT SKIN – ALL  
RAIN WATER TRAPPED



ROOF PAINT AND LAP – DRIED OUT AND  
CRACKED OR BUBBLING, ALSO LOOSE IN  
PLACES

## MORE DETAILS



RUSTED BOLT HEADS – SOME LOOSE, CRACKED ROOF SHEETS, PARAPET LEAKS – DRIED AND CRACKED, PONDING, LOOSE PAINT AND LAP.



# ECO RUBBER DETAILS

